

# MN Historical Society

## 1. Fort Snelling Revitalization: basement ceiling cracks





## 1. Fort Snelling Revitalization: tarp collecting leaking water



1. Fort Snelling Revitalization: water leak from building exterior



1. Fort Snelling Revitalization: flooding





2. Historic Sites Asset Preservation: Charles Lindbergh House (BEFORE)



2. Historic Sites Asset Preservation: Charles Lindbergh House (AFTER)






2. Historic Sites Asset Preservation: Fort Snelling, wall crack



2. Historic Sites Asset Preservation: Mill City Museum, wall restoration



2. Historic Sites Asset Preservation: Historic Forestville (southern MN), tuckpointing and wall restoration)

